



We hardened the entire end cap, while also center drilling the underside of the cap to improve ball travel alignment which extends the ball life. The cap has a 5/8" hex for easier field service removal.

